Basic Details

Series of SRR weirs came close to breaching in flood event

Publish Date

Case ID#

3120

Title

Nation

Unknown

02 September 2025

England Regulator Reference No. 310 **Legal Status** Non-statutory **Reservoir Type** Impounding **Reservoir Capacity** 10M+ m3 **Year of Construction** Unknown **Main Construction Type** Unknown **Dam Height** 5 - 9.99 metres **Dam Flood Category** Other / Not applicable **Hazard Class** Undesignated / Unclassified Reservoir Use Other **Owner Type**

Incident Details

Date & Time of Incident

02 July 2007 - 12:00

Date Incident Closed

Not provided

Observations that Caused the Incident to be Declared

- Slope or face deformation (slippage, cracking, slumps, mounds, depressions)
- Deformation or instability of crest (settlement, cracking, depressions)

Describe the Incident

A series of weirs, already in a poor condition, were damaged during a flood event. One weir in particular, about 1.5m high and impounding about 12,000m3, came close to breaching due to erosion around an abutment. It was not possible to access the sluice gate to lower the water level until the flood subsided

Supporting Photos

No images provided.

Causes and Impacts

Natural Processes which Initiated or Contributed to the Incident

• Flood - within dam design capability

Main Contributing Factors to the Incident Occurring

Dam Factors

· Deterioration of materials

External Factors

None

Shortcomings

- Surveillance shortcoming
- Maintenance shortcoming

Root Cause of the Incident

Impacts on the Reservoir

External erosion

Supporting Photos

No images provided.

Supporting Contributions and Studies

Human Factors which Influenced the Incident

Instrumentation at the Reservoir

Was Instrumentation Effective?

Not Applicable

Assistance by External Parties and Impacts on Downstream Population

None

Summary of Studies or Investigations Undertaken

Unknown

Supporting Photos

No images provided.

Lessons Learnt

Lesson 1

- Records and studies
- Surveillance and Monitoring

All tunnels under dams should be regularly inspected and any information on the design and inspection of these tunnels should be kept with the reservoir records.

Closing Comments

Supporting Photos

No images provided.

Information provided has been sent from reservoir owners and engineers, and cleansed of personal information by the enforcement authority. We cannot guarantee the accuracy of the data, but if you find an error please contact the relevant enforcement authority.